

Top Secret



DIRECTORATE OF
INTELLIGENCE

Imagery Analysis Service Notes

10 May 1968

Declass Review by NIMA/DOD

CIA internal use only

*Handle via Talent - Keyhole
Channels Only*

Top Secret

TCS 8173/68
COPY 65
PAGE 5

The IMAGERY ANALYSIS SERVICE NOTES is a periodic publication of the DDI Imagery Analysis Service, the departmental PI organization of CIA.

This publication highlights significant or timely intelligence items derived from photography.

The interpretations in this publication represent preliminary views which are subject to modification in the light of further information and more complete analysis.

WARNING

This document contains information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793, 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive information in the designated control channels. Its security must be maintained in accordance with regulations pertaining to TALENT-KEYHOLE Control System.

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

Handle Via
Talent-Keyhole
Control System Only

Approved For Release 2002/05/07 : CIA-RDP78T04759A008300010042-0

TOP SECRET RUFF
CIA INTERNAL USE ONLY
IMAGERY ANALYSIS SERVICE

TCS 8173/68

CONTENTS

Page

USSR



25X1D

NORTH VIETNAM

The Haiphong Cement Plant is Back in Operation. 5

25X1D

Next 2 Page(s) In Document Exempt

NORTH VIETNAM

The Haiphong Cement Plant is Back in Operation

Photography of [] shows a portion of the Haiphong Cement Plant in operation again for the first time since it was bombed in []. This is the only cement plant in North Vietnam.

The plant has been undergoing repairs and general cleanup during the past four months. When seen on [] an underground flue system serving two rotary kilns was complete, and one of the kilns was being repaired. On [] smoke was emanating from the flue system, indicating that one or both of the kilns were operating (see Figure 3). Dust visible at the crushing and grinding building indicated that cement was being produced.

(CONFIDENTIAL/NO FOREIGN DISSEM)




FIGURE 3. HAIPHONG CEMENT PLANT, []

Approved For Release 2002/05/07 : CIA-RDP78T04759A008300010042-0
Top Secret



Top Secret

Approved For Release 2002/05/07 : CIA-RDP78T04759A008300010042-0